




CH2MHILL
Hanford Group, Inc.

JAN 24 2001



CH2M HILL
Hanford Group, Inc.
P. O. Box 1500
Richland, WA 99352

CCN 017699C
CHG-0100413

Mr. W. J. Taylor, Assistant Manager
Systems Acquisition
U.S. Department of Energy
Office of River Protection
Post Office Box 450
Richland, Washington 99352-0450

Dear Mr. Taylor:

CONTRACT NUMBER DE-AC27-99RL14047; TRANSMITTAL OF INFORMATION
COPIES OF INTEGRATED SAFETY MANAGEMENT PLAN, REVISION 5D AND
SAFETY REQUIREMENT DOCUMENT, REVISION 3C, INCORPORATING THE U.S.
DEPARTMENT OF ENERGY OFFICE OF SAFETY REGULATION APPROVED
CHANGES FROM AUTHORIZATION BASIS AMENDMENT REQUEST,
ABAR-W375-00-00010, REVISION 0

Reference: Letter, D.C. Gibbs, ORP to M. J. Bullock, BNFL Inc., "Regulatory Unit (RU) Action in
Connection with Authorization Basis Amendment Request W375-00-00010,"
00-RU-0336/013134, dated May 2, 2000.

Attached are information copies of distribution pages of the River Protection Project-Waste
Treatment Plant (RPP-WTP) Integrated Safety Management Plan (ISMP), Revision 5d
(Attachment 1) and the Safety Requirements Document (SRD), Revision 3c (Attachment 2).


These page changes to the ISMP and SRD as presented in Authorization Basis Amendment
Request (ABAR), ABAR-W375-00-00010, Revision 0, reflect incorporation of only those
revisions to these documents that were approved by the U.S. Department of Energy (DOE)
Office of Safety Regulation (OSR). Specifically, these approved changes are those noted in
Appendix A of the Safety Evaluation Report (SER) transmitted with DOE correspondence
00-RU-0336, dated May 2, 2000. No changes to either the ISMP or the SRD were made, relative
to items in Appendix A, for which DOE approval was withheld.

To better denote the specific changes to the ISMP and SRD, Attachment 3 to this correspondence indicates which sections of 00-RU-336 SER, Appendix A provided DOE approval of the ABAR-W375-00-000010, Revision 0, changes.

While partial DOE approval of ABAR-W375-00-000010, Revision 0, proposed changes was received by BNFL Inc. several months ago, incorporation of the approved changes was not completed in a timely fashion. Although there were no safety impacts from this oversight, a deficiency report (DR-W375-01-QA00003) was prepared to address this discrepancy.

No response to this correspondence is required. Please contact Mark Platt on (509) 371-4891 for questions on this transmittal.

Very truly yours,



J. O. Honeyman, Senior Vice President
and Project Manager
Tank Waste Treatment Operations
CH2M HILL Hanford Group, Inc.

RL/MP/le

Attachments (3)